GENERAL DYNAMICS/ASTRONAUTICS A Division of General Dynamics Corporation San Diego, California 92112

X 901C

In Reply Refer To: 262-1-132 RCA:DK:ch 22 April 1964 X 64 91131

(NASA-CR-168495) LIFE SUPPORT SYSTEM FOR SPACE FLIGHTS OF EXTENDED TIME PERIODS Monthly Progress Report, 11 Mar. - 10 Apr. 1964 (General Dynamics/Astronautics) 9 p

N82-72367

Unclas 00/54 12177

Subject:

Submittel of Monthly Progress Report

for Contract IMS 1-2034

Tot

National Acronautics and Space Administration

Longley Research Center

Lengley Station

Hampton, Virginia 23365

Attention:

Contract MAS 1-2994

Englosuras

A) Ten (10) copies of Monthly Progress Report for Period of 11 March 1964 to 10 April 1964

1. The tenth mentily progress report is substitted herewith in accordance with requirements of Specification Number L-2890-A.

Project Manager

Life Buyeard System



GENERAL DYNAMICS/ASTRONAUTICS A Division of General Dynamics Corporation San Diego, California 92112

In Roply Refor To: 252-1-132 RCAIDEIGH 22 April 1964

Subject:

Submittel of Monthly Progress Report

for Contract NAS 1-2934

Tor

National Aeronautics and Space Administration

Langley Research Center

Lengley Station

Hempton, Virginia 23365

Attention:

Contract NAS 1-2934

Baclonura:

A) Ten (10) copies of Monthly Progress Report for Period of 11 March 1964 to 10 April 1964

1. The tenth menthly progress report is submitted herewith in accordance with requirements of Specification Number L-2890-A.

r. c. remaine. Project Manager

laie Support System

GENERAL DYNAMICS/ASTRONAUTICS
Life Support Project
Mail Zone 594-20
P. O. Box 166
San Diego, California 92112

X 64 91131

21 April 1964

LIFE SUPPORT SYSTEM FOR SPACE

FLIGHTS OF EXTENDED TIME PERIODS

Contract MAS 1-2934

MONTHLY PROGRESS REPORT

For Period of 11 Warch 1964 to 10 April 1964

Prepared for

Available to NASA Offices and

NASA Lengley Research Center Langley Station Hampton, Va.

This document will not be indexed or announced in Scientific and Technical Aerospace Reports. The document has received partial Descriptive

Prepared by

D. Krause

Deputy Project Manager

Approved by

R. C. Armstrong, N.D.

Project Menager

REGURD GARD ONLY

1.0 GAMERATA

- 1.1 A preliminary dreft of the LSS integrated test program was completed.
- 1.2 North American Aviation engineering personnel were questioned regarding the use of 3M series 400 paint for the Apollo interior. They confirmed that they are using this paint and that it apparently has the least material outgassing of several paints considered. It has been recommended to MASA/Lengley that we consider this paint for our program.
- 1.3 An integrated pressure sult ISS configuration was investigated. A report has been written and transmitted to NASA.
- 1.4 A design review of THV's water separator was accomplished. Authorization was given to THV to procure and fabricate all auxiliary lives of the water separator module.

2.0 THERMAL CONTROL

- 2.1 Report 64-26208, "Thermal Control Analysis" and Neport 64-26207, "Thermal Control Substitute Specification", have received a final check and are ready for final approval and reproduction. These reports reflect changes in component thermal control requirements which were current at the time the revision was started. These changes resulted in some significant vevisions in the methods of thermal control. More recent changes are not included, but they are of lesser significance and are not expected to change any of the methods or concepts.
- 2.2 The cabin air heat exchanger proposals submitted by the following vendors were evaluated:

Hamilton Standard United Aircraft Froducts Feirchild Stratos AiResearch

The unite proposed by Memilton Standard and United Aircraft Products were inadequate in performance for the LSS requirements. The unit proposed by Feirchild Strates was not applicable for the use intended. Aillesearch proposed a unit consisting of four cores of existing design manifolded together to form a single unit. The expectty of this unit was marginal with respect to the LSS requirements and the modular construction did not represent an optimized configuration for the application intended.

A connercial heat exchanger manufacturer was contacted to determine the feasibility of having a unit built to meet our specifications. The unit dimensions and secretry were determined from the performance characteristics of a similar unit used for previous in-house manuel space station testing. This connercial heat exchanger will be typically larger and heavier than a flight design.

Agreement was reached between Astronautics and NASA (Frank Booth) to procure this commercial heat exchanger rather than an off-the-shelf core designed for aircraft application. This decision was made because none of the proposed units were optimized for our conditions and the cost difference between the proposed and commercial heat exchangers were considerable.

- 2.3 Revised thermel requirements obtained from LSS component manufacturers' are being reviewed. These changes are being incorporated into the thermal control system to insure compatibility.
- 2.4 A design review of the Hohanson cooling and pumping unit and the heating and pumping unit was held. The designs were approved as modified and fabrication of the units has started.
- 2.5 A commercial type temperature control manufactured by Minneapolis Honeywell was reviewed with NASA (Frank Booth). This type will be used in the system in the interest of saving costs.
- 2.6 The off-the-shelf temperature controller by Minneapolis Moneyvell contains a believe which makes the unit unsuitable for the ISS. The Honeyvell representative suggested another one of their units which is electrically controlled and unaffected by changes in ambient pressure. This unit is now under investigation.

3.0 ATMOSPHERIC COMEROL

- 3.1 A conference was held at MASA Houston to discuss the potential problem of degradation and resulting short life of the G.E. electrolysis cell membranes. Representatives from WASA/Houston, NASA/Langley, GD/A and G.E. were present. The detailed proceedings of this conference are reported in a GD/A memo by G. L. Drake dated 31 March and a GD/Alectric Boat Memo by Dr. O. L. T. Brown dated 3 April. In general, the conferees concluded that the membrane degradation experienced in fuel cells should not be a problem in electrolysis cells, which operate under different conditions.
 - Dr. Brown did express concern over a possible concentration gradient in the stagnant electrolyte chambers of the G.E. cells. Such a gradient would increase the voltage and power requirements of the cells. G.E. was contacted regarding this problem and stated that they will check this point in their preliminary test cell stack.
- 3.2 The final design review of the reduction unit was held with TAW on April 6 and 7. The details of the meetings are included in the published minutes. Some of the more pertinent points include:
 - 1. Due to the wet Ho entering the unit, the inlet gases will be introduced upstream of the condenser separator in the recycle loop.
 - 2. The pre-cooler will be left in the recycle loop but will not be used unless it is found to be needed later.
 - 3. System shut-down provisions were added to account for the critical failures which could be foreseen by the conferees. Added items include: (a) compressor failure sint-down, and (b) reactor temperature rise shut-down.

- Integration and control studies of the oxygen reclamation system have continued. As the individual units are becoming better defined, recommendations regarding the interfaces are being made to G.E., The end Hamilton Standard. It currently appears that no active process control mechanisms are required between the three units. The reduction unit is designed to accomplish the control internally since it only functions when either CO2 or H2 are available. The concentrator will merely process all the CO2 produced by the men. The electrolysis unit continuous process rate must be set to match the net CO2 reduction rate, but it currently appears that this is feasible. More than 15% excess H2 is produced when the match is achieved and therefore the electrolysis unit need only be adjusted on a short-term basis within the 15% margin. The long-term electrolyzer adjustment to produce the required O2 can be made manually.
- 3.4 A layout of the charcoal filter and return air grill assembly was completed and a design review held. The air cooled electronic equipment simulator had been incorporated as part of the unit. Decision was made to remove the simulator to preclude possible heat damage to the charcoal filter. The assembly is being redrawn to incorporate the required changes.
- 3.5 Preliminary air distribution system arrangement sketches (594-2-25) were forwarded to obtain approval on the air distribution concept.

4.0 food, water, waste and personal hygiene

- 4.1 Two food storage modules of approximately 5 ft. long x 6 ft. high x 18" deep were requested from Whirlpool rather than a single storage rack.
- 4.2 Apparent problem areas end matters requiring clarification in the air evaporation system have been presented to and discussed with Hamilton Standard. Answers have not yet been received on the following matters:
 - 1. Problems concerning storage of hydrogen peroxide. Method of measuring and injecting $\rm H_2O_2$ into system.
 - 2. Cooling fluid requirements for water recovery rate of 1.65 lbs/kr.
 - 3. Meximum and minimum amount of CuSOn required as pretreatment chemical.
 - 4. Method of measuring and injecting CuSO, into waste waters.
- W.3 A report on the functional operation of the water management system was prepared and submitted to MASA.
- 4.4 The water storage tenk design (Astronautics) was reviewed and approved for fabrication at Astronautics.
- 4.5 The revised water management subsystem specification was typed in Timal Torm.
- 4.6 Work has commenced on the vater management subsystem feilure analysis.

- 4.7 Electric Boat's filtration unit design was approved with the exception of the physical arrangement of the canisters. A revised arrangement of the canisters (decreasing the length of the unit) was incorporated in the final design. The liquid-ges separator was removed from the unit since it is planned to store filter canisters with water so that no air carry over in the product stream will result.
- 4.8 Leyouts of the sponge squeezer and moistener were completed. Leyouts of the personal hygiene facility were started.
- 4.9 A report 64-26219, Water Menagement Subsystem Operation Description was made and submitted. This report was a detailed description of how the GD/A furnished valves were to be menigulated to obtain the various transfer routes required for the different routine and failure conditions.
- 4.10 A rough handmade RTV60 and fiberglass cloth water tenk disphragm was made in the development lab by GD/A for the purpose of running an expulsion efficiency test on this tank and bladder configuration. The bladder was heavy and thick and therefore the test was conservative. The quantity of water was carefully measured and poured into the tank. The air side of bladder was pressurized to I psi and the expelled water was again measured.

 99.6% of the water was expelled by the bladder.

5.0 COMPOIS & INSTRUMENTATION

5.1 The life support system instrumentation and control detail requirements have been compiled and assembled into a report, 64-26140, Status Famel and Ground Control Console Equipment as well as subsystem control panel equipment is called out. This report will be reproduced and submitted by the week of the 20th of April. Changes to the Instrumentation and control system as required by subsystem revisions during development will be reflected in this report as required.

6.0 TEST BED

- 6.1 The test bed was essembled and moved into the high bay area of the test leb at GD/A. The high vacuum structural tests were run satisfactorily on the main tank and sirlock. Leakage tests were run on the cable area and found to meet the spec requirements. On conculsion of the tests, it was found that the handle mechanism bearing area was unsatisfactory. CRII agreed to revork the handle for better bearing necessibating a rerun of the main tank leakage test.
- 6.2 An external stores drawing was made for purposes of providing equipment for a preliminary tank pressurization test. This test will be designed to set up a procedure for maintaining the required tank pressure and 02 and W2 partial pressures. The drawing will be modified to provide the external stores as required by the test bed leakage rates determined during the leakage tests.
- 6.3 The test bed hatch safety devices were reviewed with MASA and agreements on modifications to the hetch systems were reached. In general, the hatch systems eliminated all electrical and automatic devices putting the emphasis on manual equipment and properly trained personnel.

6.4 The test bed had been painted inside and out with zinc chromate primer per spec requirements. A subsequent finding indicated that this paint represented a potential hazard. This problem was discussed with Frank Booth and Dr. Newsom, GD/A Aerospace Medicine Group. The total toxic problem is not known at this time, however on the basis of the possibility of a toxic problem it was agreed that the zinc chromate would be removed by sand blasting and replaced with an approved paint. A 3M 400 series paint is being investigated since there has been considerable work done on this for the Apollo program. Subcontractors have been contacted for the paint removal and repainting work which will be accomplished after the hatch mods have been completed.

FORK PLANTED FOR DEXT MONTH

- 1. Thermal control coordination with subcontractors of other components and subsystems will be continued.
- 2. An Op-CO2 control procedure will be formulated.
- 3. An interface flow schematic pertinent to the O2 reclemation system control function will be formulated and sent to NASA.
- 4. A design review with G.E. on the electrolysis unit is scheduled to be held.
- 5. A preliminary design review will be held with Whirlpool on the food menagement system.
- 6. A final design review of MMD's waste management system and a preliminary design review of the torin burner will be made.
- 7. The problems associated with the air evaporation unit and the CO2 concentrator will be investigated during a trip to Hemilton Standard.
- 8. Tenk modification to rework the hatch safety mechanism will be completed prior to sand blast and pointing.
- 9. Test bed equipment rack errangement Layout will be refined with information from vendors on interface connections.
- 10. Vater management equipment rack exrangement Leyouts will be continued.
- 11. Hygiene erea arrangement layouts will be continued including detailed layout of sponge squeezer.
- 12. Instrumentation JPL's will be prepared and held for MASA's exproved of the instrumentation surmary.